

## Before



**This is a bar floor at Morisset Country Club. It had a problem with water lying around the feet of the employees. We levelled the floor with the correct fall to the drains, and then we sprayed the area with Durabond with a slip resistant finish. The job took two days and was used that night for a function.**

## After

